

GYN-0090




FIG. 1

09873574 050401
T04090 T4522860




FIG. 2a

FIG. 2b




FIG. 2c






FIG. 2d



104090 TEE2860

FIG. 3a






FIG. 3c




FIG. 3d




FIG. 4a




FIG. 4b





FIG. 4c






FIG. 4f




FIG. 4g




FIG. 4h




FIG. 4i










FIG. 4j











09873571.060401
T04090 T452860

FIG. 6b





09073571.050401
T04090" T45E4.860

FIG. 6d





FIG. 6e



[illegible]

FIG. 6f




FIG. 6g









FIG. 6h



09875571 050401
T04090 T4EEZ860









FIG. 7g

0987571.060401
T04090" T45E4860

FIG. 8a





FIG. 8d



09873571.050401
T04090 T25E4860

FIG. 8e




FIG. 8f






FIG. 8g



09073571.060401
T04090 T2554960

FIG. 8h



09873571 060404
T04090 T 4524860

FIG. 8i

